

## **GOUGAR ROAD CRASH HISTORY (2014-2018)**

## **Total of 189 Crashes**

 Most common crash type include: rear ends (109 crashes), turning (37 crashes), and fixed object (19 crashes).







**Rear End** 

**Turning** 

**Fixed Object** 

- 76 of the crashes occurred among the 4 signalized intersections, 27 crashes among the 5 unsignalized intersections, and 86 crashes along segments of Gougar Road in the study area.
- Locations with the highest occurrence of crashes include the US 30 intersection (40 crashes), the Gougar Road segment between US 30 and Francis Road (18 crashes), the Gougar Road segment between Berens Drive and Spencer Road (17 crashes), and at the Haven Avenue intersection (16 crashes).\*

Injury Type	Severity	Injury Description	# of Crashes
K	Fatal	Any injury that results in death within 30 days of crash occurrence	1
А	In- Capacitating	Any injury other than a fatal injury which prevents the injured from walking, driving, or normally continuing the activities the person was capable of performing before the injury occurred	4
В	Injury Evident	Any injury other than a fatal injury or an incapacitating injury that is evident to observers at the scene of the crash in which the injury occurred	13
С	Injury Possible	Any injury reported that is not a fatal, incapacitating, or non-incapacitating evident injury	17
PDO	Property Damage Only	Damage to property that reduces its monetary value	154



\*More detailed crash information available through the Public Engagement Period 1 materials on the website.



